Case Study

Supply and installation of Meeting Room Facility.

The project involved the removal of existing laboratory furniture and associated mechanical and electrical services. The removal of several walls and ceilings.

The re-instatement of the building services, new wall and ceiling construction, including electrical lighting. Sound System and Cat 2 lighting.

New Carpets were laid and purpose made furniture, manufactured and installed.



MRC Wellcome Building

InterFocus



